

#RB50 PARTS LIST


NOTE: Tighten into holes Before locking into other PCS.




12 PCS



12 PCS




4 PCS




TP

1 PC




TK1

2 PCS




TK2

2 PCS



TOOLS REQUIRED

STEP 2



STEP 3

